


MIDI Jacks



MIDI IN Jack does not connect to ground.

Tauntek		
New Poly61 KLM MIDI Jack Wiring		
R Grieb	Rev 1.0	Page 1 of 1
	6/11/2024	